



Number of Participants



| Pilot country | | Energy auditors | Number of energy auditors' questionnaires evaluated | Number of home owners' questionnaires evaluated |
|---------------|----------|--------------------|-----------------------------------------------------|----------------------------------------------------------|
| | Bulgaria | 7 | 13 | 10 |
| | Poland | 10 | 20 | 20 |
| | Portugal | 10 | 15 | 20 |
| | | | | |

Nearly all buildings implement a renovation measure bevor to reduce energy consumption in the previous years

Nearly all **Portuguese**homeowners have an EPC

Construction year of the buildings?

Bulgaria: 70 % of the buildings were built bevor 1970

Poland: 60 % of the buildings were built between 1970 and 1980

Portugal: 60 % of the buildings were built bevor 1970 and in the 1990s

Single-family houses




Energy Auditors



Statements on the Renovation Roadmap

To what extent do you agree with the following statement to the iBRoad Renovation Roadmap?






Energy Auditors



Statements on the iBRoad Logbook






Energy Auditors



Recommendation Rate








Homeowners



Statements on the Renovation Roadmap

To what extent do you agree with the following statement to the iBRoad Renovation Roadmap?






Homeowners



Statements on the Logbook

To what extent do you agree with the following statements related to the iBRoad Logbook?






Homeowners



Recommendation Rate

Would you recommend the iBRoad tools to your family or friends?





Results Overview


20 Portuguese Renovation Roadmap


| Pilot country | No. | Year of con- struc- tion | Number of reno- vation steps | Current energy level | Final / future energy level | Current primary energy demand [kWh/ m²] | Future primary energy demand [kWh/ m²] | Estimated date for final renovation step | Complete- ness |
|------------------|-----|-----------------------------------|---------------------------------------|----------------------------|--------------------------------------|--------------------------------------------------------|-------------------------------------------------------|------------------------------------------------|-------------------|
| | 1 | 1986 | 5 | С | A+ | 183 | 74 | 2035-2040 | complete |
| | 2 | 1500 | 5 | D | A+ | 155 | 48 | 2035-2040 | complete |
| Portugal | 3 | 1971 | 4 | 1 | | 183 | 0 | When plaster needs renovation | complete |
| | 4 | 1937 | 3 | F | A+ | 600 | 27 | 2030-2035 | complete |
| | 5 | 2001 | 3 | Α | A+ | 30 | 0 | When boiler is exchanged | complete |
| | 6 | 1937 | 4 | F | A+ | 600 | 19 | 2030-2035 | complete |
| | 7 | 1919 | 5 | D | A+ | 356 | 120 | 2025-2030 | complete |
| | 8 | 1998 | 4 | С | A+ | 116 | 0 | When plaster needs renovation | complete |
| | 9 | 1994 | 2 | A+ | Α | 145 | 112 | 2025-2030 | parts missing |
| | 10 | 2002 | 3 | С | Α | 278 | 104 | 2030-2035 | complete |
| | 11 | 1575 | 4 | D | Α | 319 | 42 | 2025-2030 | complete |
| | 12 | 1988 | 4 | F | A+ | 423 | 117 | When windows are exchanged | complete |
| | 13 | 1998 | 5 | E | B- | 203 | 0 | 2025-2030 | complete |
| | 14 | 1972 | 4 | D | B- | 387 | 250 | 2025-2030 | complete |
| | 15 | 1995 | 3 | С | Α | 176 | 19 | 2030-2035 | parts missing |
| | 16 | 1966 | 2 | E | Α | 326 | 27 | 2025-2030 | complete |
| | 17 | 1946 | 4 | F | Α | 350 | 92 | 2030-2035 | - |
| | 18 | 1989 | 5 | D | A+ | 116 | 20 | When plaster needs renovation | complete |
| | 19 | 2001 | 5 | E | Α | 192 | 19 | When plaster needs renovation | complete |
| | 20 | 1981 | 4 | С | Α | 211 | 34 | 2025-2030 | complete |



Example Roadmap







step envisages insulation measures. When the boiler needs to be exchanged it is

replaced by a biomass boiler. Energy costs drop by 88 per cent.



Results Overview

Logbook How did the auditors work?

Building information

Comfort Levels & My document and plans

Building diagnosis - Equipment

| | | | | Building diagnosis | | | | osis | | | |
|--------------------|--------------------------|------------------------------------|---------------------------------|----------------------------------------|----------------------------------------|---------------------------------------|-------------------|------------------------------|----------------|---------------|----------------|
| Pilot countries | Number of building | Number of building states | General & admin. info. | Building con- struction info. | Building energy perfor- mance | Building ope- ration and use | Comfort levels | My docu- ments & plans | | Enve- lope | Equip- ment |
| | 2 | 4 | complete | complete | complete | complete | :omplete | $\overline{}$ | - | complete | |
| Poland | 3 | 2 | partially | complete | complete | - | ı - | - | yellow | complete | - |
| | 4 | 2 | partially | complete | partially | - | | - | medium orange | complete | |
| | 5 | 1 | partially | complete | complete | partially | | - | dark red | complete | complet |
| | 6 | 1 | partially | complete | complete | complete | | - | dark red | complete | complet : |
| | 7 | 2 | partially | complete | partially | partially | | - | light green | complete | |
| | 8 | 2 | partially | complete | partially | - | ļ. | - | light green | complete | - |
| | 9 | 2 | partially | partially | partially | complete | Ŀ | upload | light green | complete | - |
| | 10 | 4 | partially | partially | partially | partially | ļ., | - | - | complete | - |
| | 11 | 1 | complete | complete | complete | - | | upload | light green | complete | partiall ' |
| | 12 | 1 | complete | complete | - | - | ļ - | upload | - | complete | - |
| | 13 | 1 | partially | partially | partially | complete | l · | . | - | complete | - |
| | 14 | 1 | partially | complete | partially | complete | ļ - | . | - | complete | - |
| | 15 | 6 | complete | complete | complete | complete | complete | upload | - | complete | partiall |
| | 16 | 7 | complete | complete | complete | complete | :omplete | upload | - | complete | complet |
| | 17 | 1 | - | - | complete | - | :omplete | - | yellow | complete | - |
| | 18 | 1 | | - | partially | - | omplete | | red | complete | |
| | 19 | 1 | partially | complete | partially | complete | :omplete | upload | - | complete | complet |
| | 20 | 1 | partially | complete | partially | complete | :omplete | | - | complete | complet |



Feedback from the Homeowners



- Positive response
- Useful functionalities
- Homeowners are motivated by the iBRoad Renovation Roadmap and Logbook to carry out renovation measures on the building





Feedback from the Energy Auditors



Manageability

- The iBRoad tools and documents have to be translated to the respective languages
- Automated data transfer between national EPC software and the Logbook
- Improve the navigation within the tools
- Printable copy of the Renovation Roadmap






Feedback from the Energy Auditors



Content

- Some auditors required more flexibility, more space for comments and descriptions in free text
- Homeowners and auditors regarded a comparison of different variants in the Roadmap as useful





Feedback from the Country Partnes



It was very hard to find enough energy auditors willing to participate

Energy auditors and home owners had difficulties to understand the iBRoad tools and concept in English language

The software could be improved via an automatic transfer of data

The iBRoad concept, in general, and the field test will require/ required a lot of extra work for energy auditors



The iBRoad tools could be more user friendly, e.g., with regard to the layout



Tool development



- Tool language: Tools are ready to be translated into different languages ✓
- Example: Auditors request an example of roadmap and logbook X
- Printable Roadmap: Auditors and homeowners wish for a hard copy of the Roadmap ✓
- Interface: Interface for data import from national calculation software to Logbook ✓ - also test in Portugal
- Navigation: Improve navigation in roadmap assistant and logbook X





Thank you very much



